







CROSS SECTION OF A TREE TRUNK AND STUMP




The tree trunk showing growth rings







© 2006 Merriam-Webster, Inc.




LOG AND TIMBER





TIMBER DEFECTS











Download from
Dreamstime.com

This watermarked comp image is for previewing purposes only.



ID 33666129

C Dule964 | Dreamstime.com










KNOTS








SECTION CUTS






www.shutterstock.com · 88984558








Rift Sawn





Quarter Sawn



Flat Sawn







LAMINATED TIMBER

